

- 1. CHANGE PARA D 2 OF REF B TO READ: CAMERA ON MODE ONE AT PT A.
- 2. SOME CONFUSION HAS EXISTED ON THE TERMINOLOGY OF THE MODIFICATION OF MODE ONE TO ELIMINATE THE TWO HIGH OBLIQUES. S. B. HMI-HP8191-SB3 INDICATES THIS IS TO BE CALLED MODE ONE FIVE POSITION.
- 3. PLS ADVISE IF YOU HAVE THIS SERVICE BULLETIN AND THE WHITE DOT PROGRAMMER INDICATED IN THE BULLETIN. HQ PLANS TO SCHEDULE THE MODE ONE/5 POSITION ON FUTURE MENS IF YOU HAVE CAPABILITY.

END OF MESSAGE

